
































ASSEMBLY INSTRUCTION

DO NOT TIGHTEN SCREWS UNTIL COMPLETELY ASSEMBLED




| | | | | |
|---|--|--|---|--|
|  ①×1PC |  ②×1PC |  ③×1PC |  ④×1PC | |
|  ⑤×1PC |  ⑥×1PC |  ⑦×1PC |  ⑧×1PC | |
|  ⑨×1PC |  ⑩×1PC |  ⑪×1PC |  ⑫×1PC | |
|  ⑬×1PC |  ⑭×2PCS |  ⑮×2PCS |  ⑯×2PCS | |
|  M6×35mm A×10PCS |  Ø15×12mm B×10PCS |  M7×40mm C×6PCS |  Ø8×30mm D×12PCS | |
|  M4×14mm E×8PCS |  M4×35mm F×4PCS |  M6×12mm G×16PCS |  M6×35mm H×4PCS | |
|  M6×40mm I×4PCS |  J×4PCS |  K×4PCS |  4mm L×1PC |  M×1PC |


1




2




3




4




5



6



7



8

